National Transportation Safety Board
FACTUAL REPORT

NTSB ID: CHI01LA326

Aircraft Registration Number: N12712

Occurrence Date: 09/27/2001

Most Critical Injury: None

Occurrence Type: Accident

Investigated By: NTSB

Location/Time

Nearest City/Place
Aurora

State
Zip Code
Local Time
Time Zone
CDT

Airport Proximity: Off Airport/Airstrip
Distance From Landing Facility:
Direction From Airport:

Aircraft Information Summary

Aircraft Manufacturer Model/Series Type of Aircraft
Cessna 208 Airplane

Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On September 27, 2001, about 0946 central daylight time, a Cessna 208, N12712, piloted by an airline transport pilot, sustained substantial damage on impact with water and a dock during a hard landing on Wynne Lake, near Aurora, Minnesota. The corporate flight was operating under 14 CFR Part 91 on an IFR flight plan. Visual meteorological conditions prevailed at the time of the accident. The pilot and six passengers were uninjured. The floatplane originated its flight from Lake Minnesota at 0830, and was landing on Wynne Lake at the time of the accident.

The pilot stated:

I lined up dogleg with the ESE Edge of the lake in order to fly close to the north shore as I touched down. Once I cleared the [obstacles] I put the ignition on, prop full, fuel on both,

flaps 20 [degrees] and checked gear up, powered back to get a good rate of descent over [obstacles] so I would not eat up the length of the lake positioning to land. (smooth surface) I came off the prop (as a brake) and began my round out higher than normal as I could feel an unusually high descent rate. In a matter seconds I could tell something was wrong as I rounded out and needed more bank angle to increase my turn rate. As I flared the plane continued to descend and the left float hit the water before I was ready and it hooked the plane immediately left about 45 [degrees] and then the rt float caught and began to slide sideways until we came to rest with the plane's tail up on the shore 90 [degrees] to the lake. I shut everything off, fuel, master, etc and exited my door[.] I opened the pass cabin door and everyone jumped onto the beach, I got their golf clubs out and they went golfing[.] ... After a while of sitting there I realized the flaps never

came

down when I put the handle down. The c/b [circuit breaker] was popped out.

A witness stated:

I first saw the plane as it came in just over the trees on the eastern shore. Just as here cleared the shoreline, the plane started to drop and bank hard to the left (or south). For

short time I could not see the plane as it was blocked by the trees on the west bank. When it came back into view it was heading south and practically on the water. It seemed to come up short on the turn, kind of bounced a pontoon off the water or a dock causing the plane to rock. When it rocked back to the left it appeared to hook or dip the left wing

into

the water or maybe a rock point causing the plane to spin to the left and sideways. It hit

middle dock, which probably slowed it down and came to rest facing back to the east, resting in shallow water leaning to the right, propped up by the right wing. It all happened

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: CHI01LA326

Occurrence Date: 09/27/2001

Occurrence Type: Accident

	Ν	larrative	(Continued)
--	---	-----------	-------------

very fast and I can't be positive of what hit what causing what.

A Cessna 208 information manual was reviewed. The manual stated, "A standby system can be used to operate the flaps in the event the primary system should malfunction."

The pilots safety recommendation stated, "Possible aural or light indication that a breaker has opened the circuit."

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: CHI01LA326

Occurrence Date: 09/27/2001

AVIATION	Occurrence Type: Accident												
Landing Facility/Approach In	formation												
Airport Name Airpo					Airport Elevat Ft.	ion MSL				way Length		Runw	ay Width
Runway Surface Type: Water							•				•		
Runway Surface Condition: Water	·glassy												
Type Instrument Approach: NONE	Ē												
VFR Approach/Landing: Full Stop													
Aircraft Information													
Aircraft Manufacturer Cessna				odel/Se 08	eries					Serial 2080	Number 0308		
Airworthiness Certificate(s): Normal													
Landing Gear Type: Amphibian													
Homebuilt Aircraft? No	·					Certified Max Gross Wt.				8360 LBS Numbe			1
Engine Type: Turbo Prop			_	Engine Manufacturer: Model/Series: Pratt & Whitney PT6-114A								Rate 675	d Power: HP
- Aircraft Inspection Information													
Type of Last Inspection			Date of	Date of Last Inspection Time Sir			Since Last Inspection			Airframe Total Time			
Annual			05/01/	05/01/2001				60 Hours			429 Hours		
- Emergency Locator Transmitter (ELT) Information												
ELT Installed? Yes	ELT Operate	ed? No	1			ELT	Aided i	n Locating Ac	cident S	ite? No	1		
Owner/Operator Information													
Registered Aircraft Owner			Stre	eet Ado	dress 301 Carls	on F	arkway	,					
Aquanaut LLC			City	City							State	- 1	Zip Code
Minnetonka Street Address									MN		55305		
Operator of Aircraft Same as Reg'd Aircraft Owner													
Same as Reg'd Aircraft Owner					City						State	€	Zip Code
Operator Does Business As: Operator Designator Code:													
- Type of U.S. Certificate(s) Held: None													
Air Carrier Operating Certificate(s)	:												
Operating Certificate: Operator Certificate:													
Regulation Flight Conducted Under: Part 91: General Aviation													
Type of Flight Operation Conducted	d: Executive/Corp	orate											
]	FACTU	JAL RE	EPOR'	Γ - AVIATI	ON							Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: CHI01LA326

Occurrence Date: 09/27/2001

AVIATI	ON	ce Type: Acc	cident								
First Pilot Information											
Name City State Date of Birth Age											Age
On File				On File			On File	Oı	n File	40	
Sex: M Seat Occupied: Left Principal Profession: Civilian Pilot Certificate Number: On File											
Certificate(s): Airline Transport											
Airplane Rating(s): Multi-engine Land; Single-engine Land; Single-engine Sea											
Rotorcraft/Glider/LTA:											
Instrument Rating(s): Airplane											
Instructor Rating(s): Airplane Multi-engine; Airplane Single-engine; Instrument Airplane											
Type Rating/Endorsement for	or Accident/In	cident Aircra	ft? No		(Current Bien	nial Flight F	Review? (9/06/2	2000	
Medical Cert.: Class 1	Medica	al Cert. Status	s: Valid Med	dicalno wa	aivers/lim.		Date of L	ast Medic	al Exan	n: 05/17/20	001
- Flight Time Matrix	- Flight Time Matrix All A/C This Mak and Mod		Airplane Single Engine	Airplane Mult-Engine	Night	Insti Actual	rument Simulated	Rotoro	raft	Glider	Lighter Than Air
Total Time	5535	400	2190	2600	1360	1400	3 (30			
Pilot In Command(PIC)	4845	400	2090	2030	1350	1350	_				
Instructor	1006	15	980	40	30						
Last 90 Days	75	45	50	25	5			_			
Last 30 Days	45	30	35	15	10	13	3	-			
Last 24 Hours	0	0	0	0	Toyio	alamı Darfa	rmod2 N -		Cooo	nd Dilat2 No	
Seatbelt Used? Yes	Snou	lder Harness	Used? Yes		TOXIC	ology Perfo	illea i Mo		Seco	nd Pilot? No)
Flight Plan/Itinerary											
Type of Flight Plan Filed: IFR											
								er De	Departure Time		Time Zone
Departure Point Lake Minnetonka State Airport Identifier Departure Time Time MN 0830 CDT									CDT		
Destination State Airport Identifier											
Same as Accident/Incident Location											
Type of Clearance: IFR											
Type of Airspace: Class G											
Weather Information											
Source of Briefing: Flight Service Station; TV/Radio Weather											
Method of Briefing: Teleph	Method of Briefing: Telephone										
			FACTUAL	REPORT -	- AVIATIO	N					Page 3

National Transportation Safety Board FACTUAL REPORT

NTSB ID: CHI01LA326

Occurrence Date: 09/27/2001

	Occurren	Occurrence Type: Accident												
Weather Information														
WOF ID	Observation Time	Tir	me Zone	WOF Eleva	tion	WOF Di	stance Fror	n Acci	dent Site		Direction From Accident Site			
EVM	0933	C	DT	1378 F	t. MSL				14 NM			270 De	g. Mag.	
Sky/Lowes	st Cloud Condition: So	attere	ed				200 Ft. AC	3L	Condition of Light: Day					
Lowest Ceiling: None				Ft	Ft. AGL Visibility: 1					SM Altimeter: 30.22				
Temperature: 8 °C Dew Point:				6 °C	Wind	Direction:	50			Density Altitude: Ft.				
Wind Spee	ed: 5		Gusts:		Weath	ner Condti	ons at Acci	dent S	ite: Visual C	Cond	itions			
Visibility (F	RVR):	t.	Visibility (R	VV)	SM	Intensity	of Precipit	ation:						
Restriction	s to Visibility: None													
Type of Pro	ecipitation: None													
Accident	Information													
Aircraft Damage: Aircraft Fire:							Aircraft Explosion				n			
Classificati	on:													
- Injury Su	mmary Matrix	F	Fatal Se	rious Min	or	None	TOTAL							
First Pi	lot					1	1							
Second	d Pilot													
Studen	t Pilot]						
Flight I	nstructor]						
Check	Pilot]						
Flight E	Engineer]						
Cabin A	Attendants							1						
Other C	Crew							1						
Passer	ngers					6	6	[
- TOTAL ABOARD -					7	7								
Other Ground								1						
- GRANE	O TOTAL -					7	7	1						
		•		•	•			-						

National Transportation Safety Board

FACTUAL REPORT AVIATION NTSB ID: CHI01LA326

Occurrence Date: 09/27/2001

Occurrence Type: Accident

Δ	dm	inis	trativ	r⊵ Int	f∩rm	ation
$\overline{}$	ulli	บบอ	uauv			alioi

Investigator-In-Charge (IIC)

Edward F. Malinowski

Additional Persons Participating in This Accident/Incident Investigation:

Glenn Bloomquist Inspector Federal Aviation Administration 6020 28th Avenue S, Room 201 Minneapolis, MN 55450